


Attachment: Sample Installation Report


Typical Professional Wireless LAN Site Survey-Installation Information Report Sheet

Location Information: Date: 8/18/05 Name: USA Toyota City: Springfield Site Contact: H. Simpson CNS Contact: Mel (888) 506-1234 Ext. 567 Surveyor's Name: Bart	Installation Information: Type of wireless connectivity: Number of AP's Installed- 2 WPA 1ad841bd1b SSID rr21643w03
---	--

Wireless Access Point Hardware: (Commercial grade)	<ul style="list-style-type: none"> • Cisco Aironet 1000  <ul style="list-style-type: none"> • Cisco Aironet Power Injector • Necessary Cabling
--	--

Access Point (1):			Access Point (2)		
IP Address	Serial #	Channel	IP Address	Serial #	Channel
172.14.122.234	FTX1926A1J6	3	172.14.122.235	FTX1926A1J8	3

Map of Strategic Wireless Access Point Placement – Result of Professional Survey/Study



Note: The red boxes display results of connectivity testing.

Installation Photos:



Access Point # 1



View of Access Point # 1



Access Point # 2



View of Access Point # 2